2025 Fire Safety Report

Per the Clery Act, an institution of higher education that maintains on-campus student housing facilities is required to publish an annual fire safety report (either as part of its annual security report or as a separate publication) by October 1 of each year. Weatherford College chooses to publish its Fire Safety Report within its Annual Security Report. The Fire Safety Report must describe Weatherford College's on-campus housing fire safety systems, contain statistics for fires that occurred in on-campus housing, and describe fire safety related policies and procedures pertaining to on-campus housing.

This fire safety report contains fire safety policies and procedures related to on-campus student housing and statistics for fires that occurred in that facility.

Fires – Summary

FIRE STATISTICS FOR ON-CAMPUS STUDENT HOUSING FACILITY					
Street Address: Coyote Village 401 College Park Drive, Weatherford, TX 76086					
Year	# of Fires	Cause of Fire	# of injuries (requiring medical Treatment)	# of Deaths Related to a fire	Property damage value
2025	0				
2024	0				
2023	0				

Fire Safety System

FIRE SAFETY SYSTEM—STUDENT HOUSING FACILITY (COYOTE VILLAGE)

Specific Building/Area Coyote Village	of	Sprinklers	Detectors (in each common area)	Detectors Individual Rooms	in	Strobes	Riser Room With Fire Pump
Community Center		Yes	Yes	Yes		Yes	Yes
Building 2		Yes	Yes	Yes		ADA Only	Yes
Building 3A		Yes	Yes	Yes		ADA Only	Yes
Building 3B		Yes	Yes	Yes		ADA Only	Yes
Building 4		Yes	Yes	Yes		ADA Only	Yes

FIRE SAFETY SYSTEM—STUDENT HOUSING FACILITY (DURANT HALL)

Specific Building/Area Durant Hall	of	Sprinklers	Detectors (in each common area)	Detectors Individual Rooms	in	Strobes	Riser Room With Fire Pump
Community Center		Yes	Yes	Yes		Yes	Yes
Building 2		Yes	Yes	Yes		Yes	No
Building 3A		Yes	Yes	Yes		Yes	No
Building 3B		Yes	Yes	Yes		Yes	No
Building 4		Yes	Yes	Yes		Yes	No